INTERNATIONAL MARITIME ORGANIZATION

4 ALBERT EMBANKMENT LONDON SE1 7SR

Telephone: 0171-735 7611 Fax: 0171-587 3210 Telex: 23588 IMOLDN G



E

Ref. T4/4.03

MSC/Circ.847/Corr.1 16 August 1999

INTERPRETATIONS OF VAGUE EXPRESSIONS AND OTHER VAGUE WORDING IN SOLAS CHAPTER II-2

Corrigenda

The following modifications are made to the interpretations contained in the annex to document MSC/Circ.847:

- 1 In regulation 18.1.1, interpretation 2, the word "interpretations" is replaced by "interpretation 2".
- In regulation 27.2, the word "interpretation 2" is replaced by "interpretations".
- In regulation 29.2, interpretation 1, the word "interpretations" is replaced by "interpretation 1".
- 4 In regulation 32.1.9.2, interpretation 1, the word "interpretations" is replaced by "interpretation".
- 5 In regulation 32.1.9.5, interpretation 1, the sentence "(See also interpretations of regulation II-2/41-2.4.3.5)" is added at the end of the interpretation.
- 6 In regulation 33.2, the existing text of the interpretation is replaced by the following:

"33.2 Reference is made to the following ISO standards:

ISO 614:1989	Shipbuilding and marine structures - Toughened safety glass panes for rectangular windows and side scuttles - Punch method of non-destructive strength testing
ISO 1095:1989	Shipbuilding and marine structures - Toughened safety glass panes for side scuttles
ISO 1751:1993	Shipbuilding and marine structures - Ships' side scuttles
ISO 3254:1989	Shipbuilding and marine structures - Toughened safety glass panes for rectangular windows
ISO 3903:1993	Shipbuilding and marine structures - Ships' ordinary rectangular windows
ISO 3904:1990	Shipbuilding and marine structures - Clear-view screens"

- In regulation 34.1, interpretation 2, the word "interpretations" is replaced by "interpretation 1".
- 8 In regulation 34.6, interpretation 1, the word "interpretations" is replaced by "interpretation 1".
- In regulation 34.6, interpretation 2, the word "interpretations" is replaced by "interpretation 2".
- In regulation 37.1.5.3, interpretation 1, the sentence "(See also interpretations of regulation II-2/38.2.3)" is added at the end of the interpretation.
- In regulation 37.1.6.3, the word "interpretations" is replaced by "interpretation".
- In regulation 37.1.6.4, the word "interpretations" is replaced by "interpretation".
- In regulation 37.3.2.2, interpretation 1, the sentence "(See also interpretations of regulations II-2/37.2.2.2 and 38.4.2)" is added at the end of the interpretation.
- In regulation 38.3.3, the word "interpretations" is replaced by "interpretation".
- 15 In regulation 38.3.4, the word "interpretations" is replaced by "interpretation".
- In regulation 38.4.1, the word "interpretations" is replaced by "interpretation".
- 17 In regulation II-2/41-2.4.5, the existing heading is replaced by "Escape stairway from machinery spaces".
- In regulation II-2/41-2.4.5, the sentence "(See also interpretation 2 of regulation II-2/29.2)" is deleted.
- 19 In regulation II-2/44.2, the words "interpretation to" are replaced by "interpretation 2 of".
- In regulation II-2/44.2, the number "27.2" is deleted.
- In regulation 45.3.1, interpretation 1, the sentence "One of the means of escape required by regulation II-2/45.3.1 should be arranged as follows:" is replaced by "If a shelter is provided, it should be arranged as follows:".
- In regulation 54.2.5, interpretation 3, the second sentence is replaced by the following:
 - "Electrical equipment in the space should comply with the International Standard IEC Publication 92-506: Electrical installations in ships Part 506: Special features Ships carrying specific dangerous goods and materials hazardous only in bulk."
- In table 58.2, note e, the words "the interpretation of" are deleted.
