#### INTERNATIONAL MARITIME ORGANIZATION

4 ALBERT EMBANKMENT LONDON SE1 7SR

Telephone: 0171-735 7611 Fax: 0171-587 3210 Telex: 23588 IMOLDN G



 $\boldsymbol{E}$ 

Ref. T5/1.01 MEPC/Circ.355 30 March 1999

## ALLEGED INADEQUACY OF PORT RECEPTION FACILITIES UNDER MARPOL 73/78

### Notification by the Government of Israel

- A notification has been received from the Government of Israel on alleged inadequacy of port reception facilities in accordance with regulation 7(4) of MARPOL Annex II.
- 2 In accordance with the above regulation, the notification is attached herewith for information.

## STATE OF ISRAEL

## 71/103. 99/1501

## Ministry of Environment

## Marine and Coastal Environment Division

 ☑ P.O.Box 33583, Haifa 31333, Israel
 ☎+972 4 8622702
 Fax:+972 4 8623524

 e-mail: marinenv@netvision.net.il

January 19, 1999

The International Maritime Organization, 4 Albert Embankment, London SE1 7SR, England.

Dear Sir/Madam.

#### Re: Alleged inadequacy of port reception facilities.

In fulfillment of our obligation under regulation 7(4) of Annex II to the MARPOL convention, we hereby notify you as follows:

The chemical tanker TURCHESE arrived in Israel on January 17 1999, carrying on board 33 Cubic Meters of effluent originating from cargo tanks pre-wash. The vessel was unable to discharge the effluent in the unloading port due to alleged inadequacy of port reception facilities.

Enclose please find the vessel's report.

Sincerely yours,

Ellik Adler

Head of Marine and Coastal Environment Division

Received
Routing 28 JAN 1999

No action

HK action

action or answered

for filing

# REVISED CONSOLIDATED FORMAT FOR REPORTING ALLEGED INADEQUACY OF PORT RECEPTION FACILITIES\*

The Master of a ship having difficulties in discharging waste to reception facilities should forward the information below, together with supporting documentation, to the competent authority of the flag State.

1.	SHIP'S PARTICULARS
	Name of ship: TURCHESE
	Owner or operator: O. H. MEHLING & CO. AS
	Distinctive number or letters: ELVU 6 (CALL SIGN)
	Port of registry: MONROVIA
	Type of ship:oil tanker, chemical tanker, passenger ship, cargo ship
	orother (specify)
2.	PORT PARTICULARS
	Country: ITALY
	Name of Port or Area: SARROCH
	Location/Terminal Name: A2 - BERTH
	(e.g. berth/terminal/jetty)
	Name of company operating reception facility (if applicable):
	X Unloading port, Loading port, Shipyard
	Date of arrival: OS - JAN - 99
	Date of incident:
	Date of incident:  Date of departure: 09 — JAN - 99
3.	TYPE AND AMOUNT OF WASTE FOR DISCHARGE TO FACILITY
3.1	Oil (MARPOL Annex I)
J.1	Type of oily waste:
	bilge water m
	sludge from fuel oil purifier m
	scale and sludge from tanker cleaning m
	dirty ballast water m
	tank washings m
	other (specify) m
	outer (observi);
*	This format was developed and approved by the forty-second session of the Marine Environment

Protection Committee in November 1998.

Type of NLS residue/water mixture for discharge to facility from prewash of:	ייו כי גרי
category A substance "COUPE C-7" - PREWASH / WATER	_ <del>5</del> 32° _ m³
category B substance	_ m <sup>3</sup>
category C substance	- ''' m³
other (specify)	- '''
Substance is designated as solidifying or high viscosity	11
Name of the noxious liquid substance involved: "COUPE - C-7" CAT "A	
Garbage (MARPOL Annex V)	
Type of garbage:	
mixed garbage	_ m
food wastes	_ m <sup>3</sup>
cargo associated waste	_ m
maintenance waste	_ m
other (specify)	_ m
PREWASH - WATER MIXTURE , 33 CBM	
ADEQUACY OF FACILITIES	
ADEQUACY OF FACILITIES Facilities available  Yes N	
ADEQUACY OF FACILITIES	
ADEQUACY OF FACILITIES Facilities available  Yes N	
ADEQUACY OF FACILITIES Facilities available  Yes N	
ADEQUACY OF FACILITIES Facilities available  Yes N	0 >
ADEQUACY OF FACILITIES  Facilities available  Yes N  Remarks (e.g. brief report on good or bad experience)  Location of facilities (close to the vessel, inconvenient location or vessel had to shift berth involved.)	0 ×

Prior to arrival at the port, did you notify agent or authorities about the vessels reception facilities?	Yes <u>×</u>	
Did you receive information on the availability of reception facilities on arrival?	Yes	No_
COSTS INCURRED, OR CONFIRM FREE OF CHARGE		
If known to you, are the reception facilities owned or operated by:  Port Authorities Private firm		
Is garbage removal compulsory?	Yes	No_
ANY ADDITIONAL REMARKS/COMMENTS		
m/t "TURC	HESE"	
CHIEF OFFI	CER	$oldsymbol{eta}$
Name of ship's officer in charge	CER	

#### COPENOR G.I.E.

## SAFETY DATA SHEET

Product: COUPE C7 Page: 1/5

Pallution Categorie A 👔

OT - IDENTIFICATION OF THE SUBSTANCE PREPARATION AND THE COMPANY/UNDERTAKING

PRODUCT NAME COUPE C7
PRODUCT CODE 01:294

SUPPLIER COPENCR G.I.E.

route des Dunes - 32 53 53179 LOON-PLAGE

FRANCE

Täléphane: G2 29 62 74 00 Täléphane: G2 29 62 75 00

Emergancy talapone number GZ 23 82 75 58

CZ - COMPOSITION / INFORMATION ON INGREDIENTS

CHEMICAL NAME OF THE SUBSTANCE C7 dut

- Taluene, 35% (approximately)
- C3 (xylene, sthylbenzene), 25%
- C3 nonaromadque (alkylata), 46%

GENERIC NAME Hydrocarbans
CAS 108.38.3

ENECS 103.38.3 ENECS 203.525.9

02-YAZAROS IDENTIFICATION -

MOST IMPORTANT HAZARDS SAFETY IMPORMATION : PLEASE READ THIS SHEET CAREFULLY

HEALTH EFFECTS May cause cancer.

Harmful if swellowed.

PHYSICAL AND CHEMICAL HAZAROS Hammable liquid.

Thermal decomposition gives: Greanic derivatives

SPECIFIC HAZEROS / EEC HIGHLY FLAMMABLE

TOXIC

Harmful if swalawed.

C4 - FIRST AID MEASURES

GENERAL ACVICE Take all immediately all contaminated digiting.

INHALATION Move to fresh air.

Oxygan ar araficial respiration if needed.

Hospitaliza immediately.

SKIN CONTACT Wash immediately and soundandy with soap and water.

It significant contact : mospituliza immediataly.

COPENCR SILE FAUTO SEE SUPER - 88 59 F. 59279 LOCALAGE FRANCE