
4 ALBERT EMBANKMENT
LONDON SE1 7SR
Telephone: +44 (0)20 7735 7611 Fax: +44 (0)20 7587 3210

MEPC.1/Circ.801
24 January 2013

IMPLEMENTATION AND ENFORCEMENT OF MARPOL ANNEX VI

Bunker delivery note and fuel oil sampling

Communications received from the Administrations of Cyprus, France, Liberia, Norway, Vanuatu and Hong Kong, China

- 1 Communications have been received from the Administrations of Cyprus, France, Liberia, Norway, Vanuatu and Hong Kong, China concerning the application of provisions under MARPOL Annex VI.
- 2 In accordance with the provisions of regulation 18.9.6 of MARPOL Annex VI, the above-mentioned communications, summarized in the annex, are circulated to Parties to the 1997 Protocol for their information and appropriate action, as well as to all IMO Members.
- 3 Reference should be made to MEPC.1/Circ.508 on bunker delivery notes and fuel oil sampling, and resolution MEPC.96(47) on *Guidelines for the Sampling of Fuel Oil for Determination of Compliance with Annex VI of MARPOL 73/78*.
- 4 For further details, please contact the flag State Administrations, the bunkering port Authorities or the marine fuel oil supplier.

ANNEX

SUMMARY OF NOTES OF PROTEST RELATED TO MARPOL ANNEX VI
RECEIVED FROM JULY TO DECEMBER 2012

Notes of protest received from the Administration of Cyprus

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
KONRAD SCHULTE 9292125	Khor fakkan, United Arab Emirates*, 9.1.2012	MTI Oil Marketing & Trading Intl, P.O. Box 17540 Suite 502, Al Shurooq Bldg Kalba, Sharjah, U.A.E., Tel: +971 9 2281201 Fax: +971 9 2281202	The sulphur content on BDN: 3.40% m/m, The sulphur content after supplied and tested: 3.63% m/m
BALTIC FAITH 9327360	Tenerife, Spain, 13.1.2012	SEPSA Marine S.A., -----, Tel: +34 91 337 6852	The sulphur content on BDN: 1.00% m/m, The sulphur content after supplied and tested: 1.12% m/m
IOANNIS I 9281580	New York, United States, 18.1.2012	HESS Corporation -----, Tel: +1 732 750 6000	The sulphur content on BDN: 0.96% m/m, The sulphur content after supplied and tested: 1.14% m/m
HANSE SPIRIT 9302255	Rotterdam, Netherlands, 4.2.2012	Argos Ceebunkers B.V., Tel : +31 10 2954780, Fax: +31 10 2954781 e-mail: bunkers@argos.nl	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.06% m/m
LOUKAS 1 9281578	Barcelona, Spain, 16.2.2012	CEPSA Marine Fuels S.A., -----, Fax: +34 91 337 6027	The sulphur content on BDN: 0.92% m/m, The sulphur content after supplied and tested: 1.10% m/m
BALTIC FAITH 9327360	Fredrikshavn, Denmark, 23.2.2012	O.W. Bunker & Trading A/S, -----, Fax: +45 98 16 7277 E-mail: owbunker@owbunker.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.08% m/m
HANSE SPIRIT 9302255	Rotterdam, Netherlands, 8.3.2012	Associated Bunkeroil Contractors B.V., -----, Fax: +31 10 436 0439 e-mail: info@abc-house.com	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.04% m/m
KONRAD SCHULTE 9292125	Khor fakkan, United Arab Emirates*, 25.3.2012	MTI Oil Marketing & Trading Intl, P.O. Box 17540 Suite 502, Al Shurooq Bldg Kalba, Sharjah, U.A.E., Tel: +971 9 2281201 Fax: +971 9 2281202	The sulphur content on BDN: 3.10% m/m, The sulphur content after supplied and tested: 3.53% m/m

* Not Party to the 1997 Protocol (MARPOL Annex VI) at the time of the bunkering.

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
HANSE SPIRIT 9302255	Rotterdam, Netherlands, 26.4.2012	O.W. Bunker (Netherlands) B.V., Waalhaven OZ.83 Gebouw 1 NL-3087 BM Rotterdam Netherlands, Tel: +31 10 789 1111 Fax: +31 10 495 5540 e-mail: owbunker@owbunker.nl	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m
MATTHEOS I 9281554	Rotterdam, Netherlands, 1.7.2012	Aegean Northwest Europe, -----, Fax: +32 3 652 0608	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.12% m/m
HANSE SPIRIT 9302255	Rotterdam, Netherlands, 1.7.2012	Aegean Northwest Europe, -----, Fax: +32 3 652 1422	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
CMA CGM UTRILLO 9192430	Rotterdam, Netherlands, 5.7.2012	Aegean Northwest Europe, -----, Fax: +32 3 652 1422	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.00% m/m
HANSA VISION 9302243	St. Petersburg, Russian Federation, 1.8.2012	ANDIYA Ltd., -----, Tel: +7 812 331 74 30 Fax: +7 812 331 74 30	The sulphur content on BDN: 0.96% m/m, The sulphur content after supplied and tested: 1.03% m/m
HANSE SPIRIT 9302255	Rotterdam, Netherlands, 3.8.2012	Associated bunker oil Contractors, -----, Tel: +31 10 436 05 33 Fax: +31 10 436 04 39 e-mail: info@abc-house.com	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.03% m/m
RUTH 9376036	Antwerp, Belgium, 7.8.2012	O.W. Bunker (Belgium) N.V., -----, Tel: +30 288 3600 Fax: +30 234 1874 e-mail: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.08% m/m
CMA CGM MATISSE 9192428	Rotterdam, Netherlands, 12.8.2012	O.W. Bunker (Netherlands) B.V., -----, Tel: +31 10 789 1111 Fax: +31 10 495 5540 e-mail: owbunker@owbunker.nl	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.01% m/m
RN PRIIVODINO 9384459	Arkhangelsk, Russian Federation, 18.8.2012	RN Bunker Russia, -----, Tel: +7 495 755 52 43 Fax: +7 495 755 52 43	The sulphur content on BDN: 0.997% m/m, The sulphur content after supplied and tested: 1.02% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
RN MURMANSK 9384447	Arkhangelsk, Russian Federation, 18.8.2012	RN Bunker Russia, -----, Tel: +7 495 755 52 43 Fax: +7 495 755 52 43	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.04% m/m
HANSE SPIRIT 9302255	Rotterdam, Netherlands, 1.9.2012	Aegean North West Europe, -----, Fax: +32 3 652 1422 e-mail: ara.bunkers@ampni.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
TRANSJORUND 9349227	Hamburg, Germany, 18.9.2012	O.W. Bunker Germany GmbH, -----, Tel: +49 40 32 55 90 Fax: +49 40 33 04 71	The sulphur content on BDN: 1.00% m/m, The sulphur content after supplied and tested: 1.09% m/m
CMA CGM UTRILLO 9192430	Rotterdam, Netherlands, 23.9.2012	Lukoil Benelux B.V. -----, Tel: +31 10 264 2700 Fax: +31 10 264 2750	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.00% m/m
HANSE SPIRIT 9302255	Rotterdam, Netherlands, 23.9.2012	Associated bunkeroil Contractors, -----, Tel: +31 10 436 05 33 Fax: +31 10 436 04 39 e-mail: info@abc-house.com	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m
RN ARKHANGELSK 9384435	Rotterdam, Netherlands, 4.10.2012	Associated bunkeroil Contractors, -----, Tel: +31 10 436 05 33 Fax: +31 10 436 04 39 e-mail: info@abc-house.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
HANSE SPIRIT 9302255	Rotterdam, Netherlands, 13.10.2012	Argos Bunkering B.V.,, -----, Tel: +31 88 1007 630 Fax: +31 88 1007 920 e-mail: bunkering@argosenergies.com	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.06% m/m
RN ARKHANGELSK 9384435	Arkhangelgk, Russian Federation, 12.10.2012	RN Bunker, -----, Tel: +7 495 755 52 43 Fax: +7 495 755 52 43	The sulphur content on BDN: 0.96% m/m, The sulphur content after supplied and tested: 1.11% m/m
RN MURMANSK 9384447	Arkhangelsk, Russian Federation, 12.10.2012	RN Bunker, -----, Tel: +7 495 755 52 43 Fax: +7 495 755 52 43	The sulphur content on BDN: 0.96% m/m, The sulphur content after supplied and tested: 1.07% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
HANSA VISION 9302243	Rotterdam, Netherlands, 23.10.2012	O.W. Bunker (Netherlands) B.V., -----, Tel: +31 10 789 1111 Fax: +31 10 495 5540	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.04% m/m
CMA CGM MANET 9224958	Rotterdam, Netherlands, 20.10.2012	Lukoil Benelux B.V., -----, Tel: +31 10 264 2700 Fax: +31 10 264 2750	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
RN PRIVODINO 9384459	Amsterdam, Netherlands, 29.10.2012	Argos Bunkering B.V., -----, Tel: +31 88 1007 630 Fax: +31 88 1007 920 e-mail: bunkering@argosenergies.com	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.05% m/m
CMA CGM MATISSE 9192428	Rotterdam, Netherlands, 4.11.2012	Shell Nederland Raffinaderij B.V., -----, Tel: +31 10 431 7482	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.04% m/m
RN PRIVODINO, 9384459	Amsterdam, Netherlands, 19.11.2012	Oliehandel Klaas de Boer b.v., -----, Tel: +31 255 513240 e-mail: ljmuiden@klaasdeboer.nl	Sample was not taken at the receiving ship's manifold.
CMA CGM UTRILLO 9192430	Rotterdam, Netherlands, 22.12.2012	Argos Bunkering B.V., -----, Tel: +31 88 1007 630 Fax: +31 88 1007 920 e-mail: bunkering@argosenergies.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
HANSE SPIRIT 9302255	Rotterdam, Netherlands, 28.12.2012	Argos Bunkering B.V., -----, Tel: +31 88 1007 630 Fax: +31 88 1007 920 e-mail: bunkering@argoenergies.com	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.06% m/m

Notes of protest received from the Administration of France

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
CMA CGM MOZART 9280615	Singapore, 16.9.2012	Consort Bunkers Pte Ltd, 31 Hong Kong Street Singapore 059670, Tel: +65 6344 3008 Fax: +65 6344 5745	The sulphur content on BDN: 3.46% m/m, The sulphur content after supplied and tested: 3.69% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
CMA CGM CHOPIN 9280603	Marsaxlokk, Malta, 7.10.2012	Sun Lucian Oil Company Ltd, 42 Spencer Hill MRS 1955 Marsa Malta, -----	The sulphur content on BDN: 1.00% m/m, The sulphur content after supplied and tested: 1.02% m/m
CMA CGM CHOPIN 9280603	Rotterdam, Netherland, 16.10.2012	Lukoil Benelux B.V., P.O. Box 24065 3007 DB Rotterdam Wilhelminakade 85 3072 AP Rotterdam Maastoren building 36the floor Netherlands -----	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.02% m/m
CMA CGM CHOPIN 9280603	Antwerp, Belgium, 20.10.2012	Shell Nederland Raffinaderij B.V., Vondelingenweg 601 3156 KK Hoogvliet Rotterdam Netherlands, Tel: +31 104317479	The sulphur content on BDN: 3.39% m/m, The sulphur content after supplied and tested: 3.60% m/m
CMA CGM PUCCINI 9280627	Rotterdam, Netherlands, 30.10.2012	Argos Bunkering B.V., Waalhaven ZZ. 11 3089 JH Rotterdam P.O. Box 59083 Netherlands, Tel: +31 88 1007 630	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m

Notes of protest received from the Administration of Liberia

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
NS CHAMPION 9299719	Rotterdam, Netherlands, 21.6.2012	RMF, -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m
FRONT SERENADE 9248473	Singapore, 28.6.2012	G-Fuel Pte Ltd, 52A Duxton Rd 189516 Singapore, Tel: +65 6225 0777 Fax: +65 6224 0777	The sulphur content on BDN: 3.42% m/m, The sulphur content after supplied and tested: 3.58% m/m
W-EAGLE 9484675	Amsterdam, Netherlands 30.6.2012	Oliehandel KLAAS DE BOER, Trawlerkade 58 1976 CB IJmuiden Netherlands, Tel: +31 255 513240	The sulphur content on BDN: 3.37% m/m, The sulphur content after supplied and tested: 3.66% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
MOL SATISFACTION 9179828	Singapore, 8.7.2012	BP Singapore Pte Limited, 1 Harbour Front Avenue #02-01 Keppel Bay Tower 098632 Singapore, Tel: +65 6371 8888 Fax: +65 6278 1565	The sulphur content on BDN: 3.38% m/m, The sulphur content after supplied and tested: 3.56% m/m
POLARIS J 9457000	Sines, Portugal, 7.7.2012	galp energia, Rua Tomas da Fonseca 1600-209 Lisboa Portugal, Tel: +351 21 724 25 00	The sulphur content on BDN: 0.96% m/m, The sulphur content after supplied and tested: 1.30% m/m
SCF PACIFICA 9577068	Amsterdam, Netherlands 17.7.2012	Argos Bunkering B.V., Waalhaven Z.Z. 11 3089 JH Rotterdam Netherlands, Tel: +31 88 1007 630 Fax: +31 88 1007 920	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.10% m/m
CARLOTTA STAR 9210050	Antwerp, Belgium, 22.7.2012	O.W. Bunker, Tavernierkaai 2 2000 Antwerpen Belgium, Tel: +32 3 288 3600	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.07% m/m
HANSA RENDSBURG 9155377	Antwerp, Belgium, 27.7.2012	Oil Chart, Plantinkaai 13 2000 Antwerpen Belgium, Tel: +32 3 232 52 34 Fax: +32 3 233 67 45 e-mail: info@oilchart.com	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.08% m/m
HANSA CASTELLA 9152595	Singapore, 7.8.2012	BP Singapore Pte Limited, 1 Harbour Front Avenue #02-01 Keppel Bay Tower 098632 Singapore, Tel: +65 6371 8888 Fax: +65 6278 1565	The sulphur content on BDN: 3.39% m/m, The sulphur content after supplied and tested: 3.63% m/m
CMA CGM AUCKLAND 9344564	Cartagena, Colombia, 21.8.2012	CODIS, Centro Comercial Mamonal Plaza I-Local 11 Cartagena Colombia, Tel: +57 5 6673951 e-mail: gerencia@codis.com.co	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.09% m/m
OLYMPIYSKY PROSPECT 9511387	UST-LUGA, Russian Federation, 12.9.2012	Lukoil, -----, -----	The sulphur content on BDN: 0.95% m/m, The sulphur content after supplied and tested: 1.03% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
SCF TOMSK 9326598	Jeddah, Saudi Arabia, 16.9.2012	BAKRI International Co. Ltd., P.O. Box 3757 Jeddah 21481 Saudi Arabia, Tel: +966 2 6516666 Fax: +966 2 6526018 e-mail: info@bakrienergy.com	The sulphur content on BDN: 3.34% m/m, The sulphur content after supplied and tested: 3.57% m/m
SCF PROVIDER 9577094	Antwerp, Belgium, 29.9.2012	Oilchart, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.06% m/m
FRONT COMMODORE 9176993	Singapore, 4.10.2012	-----, -----, -----	The sulphur content on BDN: 3.39% m/m, The sulphur content after supplied and tested: 3.54% m/m
PETRODVORETS 9186596	Rotterdam, Netherlands, 6.10.2012	AEGEAN NEW N.V., Nijverheidsstraat 7 B-2960 St. Job in't Goor Belgium, Tel: +32 3 652 06 08	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.06% m/m
BELLA SCHULTE 9453365	Rotterdam, Netherlands 12.10.2012,	Petrobras Global Trading B.V., Weenapoint Toren A Weena 722. 4e verdieping 3014 DA Rotterdam Netherlands, Tel: +31 10 2067060 Fax: +31 10 2067095	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.06% m/m
TORGOVY BRIDGE 9292046	Antwerp, Belgium, 19.10.2012	Oilchart, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.05% m/m
FPMC 30 9581679	Panama City, Panama, 30.10.2012	CEPSA Panama, -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.19% m/m
SCF SURGUT 9422445	Rotterdam, Netherlands, 1.11.2012	WILJO, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m

Notes of protest received from the Administration of Norway

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
STEN AURORA 9318565	Antwerp, Belgium, 7.1.2012	Wiljo B.V, -----, Tel: +32 406 494 039 e-mail: Wiljo@Wiljo.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.06% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
HÖEGH TREASURE 9184859	Rotterdam, Netherlands, 3.1.2012	NORTH SEA GROUP BUNKERING B.V., -----, -----	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.04% m/m
STEN BALTIC 9307671	Rotterdam, Netherlands, 8.1.2012	O.W. Bunker, -----, e-mail: owbunker@owbunker.nl	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.06% m/m
HÖEGH ASIA 9191876	Barcelona, Spain, 4.1.2012	RYTTSA Bunker REPSOL, -----, -----	The sulphur content on BDN: 0.94% m/m, The sulphur content after supplied and tested: 1.06% m/m
HÖEGH ASIA 9191876	Rotterdam, Netherlands, 11.1.2012	Maersk Oil Trading, -----, Tel: +45 3363 3363	The sulphur content on BDN: 3.42% m/m, The sulphur content after supplied and tested: 3.58% m/m
HÖEGH OSLO 9382396	Bremerhaven, Germany, 27.1.2012	Wrist Bunker Supply GmbH, -----, Tel: +49 4032 5590-0	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
DYVI ADRIATIC 8519710	Antwerp, Belgium, 7.2.2012	Oil Chart Bunkering, -----, e-mail: info@oilchart.com	The sulphur content on BDN: 1.0% m/m, The sulphur content after supplied and tested: 1.08% m/m
SKS TIETE 9172650	Rotterdam, Netherlands, 12.2.2012	NIOC Bunkering B.V., -----, e-mail: niocbunkering@planet.nl	The sulphur content on BDN: 3.43% m/m, The sulphur content after supplied and tested: 3.64% m/m
STEN BALTIC 9307671	Amsterdam, Netherlands, 23.2.2012	Lukeoil Benelux B.V., -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.07% m/m
STEN NORDIC 9351567	Rotterdam, Netherlands, 12.02.2012	Argos Oil, -----, e-mail: bunkers@argos.nl	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.04% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
STEN NORDIC 9351567	Rotterdam, Netherlands, 27.2.2012	LUKOIL Benelux BV., -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
BERGE DANUTA 9193721	Gibraltar, 24.2.2012	PENINSULA, -----, -----	The sulphur content on BDN: 0.94% m/m, The sulphur content after supplied and tested: 1.03% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
STEN BALTIC 9307671	Rotterdam, Netherlands, 16.3.2012	RMF, Rotterdam Marine Fuels B.V., -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m
STEN AURORA 9318565	Antwerp, Belgium, 10.3.2012	Verbeke Bunkering NV, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.01% m/m
BW DANUTA 9193721	Gibraltar, 25.2.2012	Peninsula Petroleum, -----, e-mail: bunkers@peninsulapetroleum .com	The sulphur content on BDN: 0.94% m/m, The sulphur content after supplied and tested: 1.03% m/m
MV FAVORITA 9298519	Singapore, 14.3.2012	Lian Hoe Leong & Brothers Pte Ltd., -----, -----	The sulphur content on BDN: 3.43% m/m, The sulphur content after supplied and tested: 3.98% m/m
HÖEGH ST. PETERSBURG 9420045	Rotterdam, Netherlands, 19.2.2012	Petrobras Global Trading B.V., -----, -----	The sulphur content on BDN: 0.94% m/m, The sulphur content after supplied and tested: 1.02% m/m
BOW SAGA 9215309	Rotterdam, Netherlands, 1.3.2012	NIOC Bunkering B.V., -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.04% m/m
HÖEGH TROPICANA 7903093	Amsterdam, Netherlands, 22.3.2012	Oliehandel KLAAS DE BOER, -----, -----	The sulphur content on BDN: 3.39% m/m, The sulphur content after supplied and tested: 3.62% m/m
STEN AURORA 9318565	Rotterdam, Netherlands, 2.4.2012	Argo's Ceebunkers BV, -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
HÖEGH TRANSPORTER 9176395	Barcelona, Spain, 22.3.2012	CEPSA Marine fuels, S.A., -----, -----	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.06% m/m
STAV VIKING 9401556	Rotterdam, Netherlands, 25.3.2012	Cockett Marine Oil Limited, -----, -----	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.02% m/m
STAV VIKING 9401556	Antwerp, Belgium, 18.4.2012	Transcor Energy SA, -----, -----	The sulphur content on BDN: 0.967% m/m, The sulphur content after supplied and tested: 1.05% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
EK-SKY 9164512	Rotterdam, Netherlands, 23.3.2012	Argos Oil, -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.06% m/m
HÖEGH BANGKOK 9318474	Gdansk, Poland, 4.4.2012	Ship Service SA, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
SKS TAGUS 9133458	Singapore, 28.4.2012	Chemi Oil Int., -----, -----	The sulphur content on BDN: 3.31% m/m, The sulphur content after supplied and tested: 3.53% m/m
HÖEGH DETROIT 9312470	Masan, South Korea, 28.4.2012	S-Oil Corporation, -----, -----	The sulphur content on BDN: 3.33% m/m, The sulphur content after supplied and tested: 3.52% m/m
HÖEGH ASIA 9191876	Piraeus, Greece, 29.4.2012	Aegean Oil S.A., -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.03% m/m
HÖEGH COPENHAGEN 9420057	Singapore, 30.4.2012	Trans Ocean Oil Pvt Ltd, -----, -----	The sulphur content on BDN: 3.49% m/m, The sulphur content after supplied and tested: 3.62% m/m
EKEN 9286827	Rotterdam, Netherlands, 23.4.2012	RMF, -----, -----	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.04% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
STAR JAVA 9310513	Flushing, Netherlands, 24.4.2012	Wiljo, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.08% m/m
BOW CECIL 9143219	Rotterdam, Netherlands, 1.6.2012	Chemoil Europe BV, -----, Tel: +31 102 929 933	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
JO ASK 9125126	Rotterdam, Netherlands, 23.4.2012	O.W. Bunker, -----, e-mail: owbunker@owbunker.nl	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.01% m/m
HÖEGH COPENHAGEN 9420057	Zeebrugge, Belgium, 27.5.2012	Total Marine Fuel, -----, Tel: +32 2288 9234	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.08% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
BOW CHAIN 9214317	Houston, United States, 1.6.2012	Chemoil Cooperation, -----, e-mail: ops@chemoil.com	The sulphur content on BDN: 0.88% m/m, The sulphur content after supplied and tested: 1.37% m/m
HÖEGH OSLO 9382396	Amsterdam, Netherlands, 13.6.2012	Oliehandel KLAAS DE BOER, -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.05% m/m
STAV VIKING 9401556	Antwerp, Belgium, 24.7.2012	Transcor Energy N.V/S.A, -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.06% m/m
HÖEGH TRAVELLER 8116908	Amsterdam, Netherlands, 22.7.2012	ARGOS BUNKERING. B.V., -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.14% m/m
STEN NORDIC 9351567	Rotterdam, Netherlands, 4.8.2012	LUKOIL Benelux BV, -----, e-mail: bunkers@lukoil.nl	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
SKS TORRENS 9161273	Rotterdam, Netherlands, 2.8.2012	Aegean North West Europe, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.10% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
BOW FORTUNE 9168635	Antwerp, Belgium, 27.7.2012	Maritime Bunkering & Trading BVBA, -----, -----	The sulphur content on BDN: 0.09% m/m, The sulphur content after supplied and tested: 0.11% m/m
BOW RIYAD 9047506	Antwerp, Belgium, 7.8.2012	Aegean North West Europe, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.10% m/m
HÖEGH DETROIT 9312470	Singapore, 16.8.2012	BP Singapore Pte. Ltd., -----, -----	The sulphur content on BDN: 3.39% m/m, The sulphur content after supplied and tested: 3.62% m/m
BOW SIRIUS 9215294	Rotterdam, Netherlands, 15.8.2012	O.W. Bunker, -----, e-mail: owbunker@owbunker.nl	The sulphur content on BDN: 0.96% m/m, The sulphur content after supplied and tested: 1.04% m/m
STAVANGER PRINCESS 9231468	Rotterdam, Netherlands, 24.8.2012	Aegean North West Europe, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
STEN HIDRA 9358931	Amsterdam, Netherlands, 8.9.2012	LUKOIL Benelux BV, -----, e-mail: bunkers@lukoil.nl	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
BOW FAITH 9114232	Gibraltar, 1.10.2012	Peninsula, Gibraltar, -----, -----	The sulphur content on BDN: 0.10% m/m, The sulphur content after supplied and tested: 0.14% m/m
STEN NORDIC 9351567	Rotterdam, Netherlands, 7.10.2012	Aegean North West Europe, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m
BOW BRACARIA 9114775	Antwerp, Belgium, 1.10.2012	Aegean North West Europe, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.05% m/m
STEN NORDIC 9351567	Riga, Latvia, 16.11.2012	Fast Bunkering Ltd., -----, -----	The sulphur content on BDN: 0.90% m/m, The sulphur content after supplied and tested: 1.02% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
SKS TANA 9116967	Ijmuiden, Netherlands, 11.11.2012	Wiljo, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
BOW BRACARIA 9114775	Antwerp, Belgium, 17.11.2012	Transcor, -----, -----	The sulphur content on BDN: 0.95% m/m, The sulphur content after supplied and tested: 1.02% m/m
HÖEGH SINGAPORE 9431862	Galveston, United States 14.11.2012	BP Products North America Inc., -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.03% m/m
SKS TAGUS 9133458	UST Luga, Russia, 21.11.2012	Gazprom, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.03% m/m
STAV VIKING 9401556	Rotterdam, Netherlands, 22.11.2012	Transcor Energy SA, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.03% m/m
STEN BALTIC 9307671	Rotterdam, Netherlands, 25.11.2012	Rotterdam Marine Fuels, -----, -----	The sulphur content on BDN: 0.96% m/m, The sulphur content after supplied and tested: 1.02% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
STEN HIDRA 9358931	Anwerp, Belgium, 2.12.2012	O.W. Bunker (Belgium) N.V., -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.01% m/m
BOW EAGLE 8112914	Tenerife, Spain, 5.12.2012	CEPSA Marine Fuels, -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m
BOW CEDAR 9087013	Rotterdam, Netherlands, 19.12.2012	Argos Bunkering B.V., -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
STEN BALTIC 9307671	Amsterdam, Netherlands, 17.12.2012	Aegean North West Europe, -----, -----	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.04% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
HÖEGH ASIA 9191876	Barecelona, Spain, 18.12.2012	Repsol Ypf Trading Y Transportes SA, -----, -----	The sulphur content on BDN: 0.92% m/m, The sulphur content after supplied and tested: 1.04% m/m
STAV VIKING 9401556	Svetly, Russia, 20.12.2012	Arte Bunkering OU, -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.03% m/m
HÖEGH MANILA 9368912	Piraeus, Greece, 18.12.2012	MAMIDOIL JETOIL, -----, -----	The sulphur content on BDN: 0.96% m/m, The sulphur content after supplied and tested: 1.02% m/m
SKS MOSEL 9240433	Gibraltar, 10.12.2012	CEPSA MARINE FUELS, -----, -----	The sulphur content on BDN: 0.81% m/m, The sulphur content after supplied and tested: 1.12% m/m
BOW FLOWER 9047491	Balboa, Panama, 26.12.2012	Bominflot Inc., -----, -----	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.03% m/m

Notes of protest received from the Administration of Vanuatu

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
GSF ARTIC 1 8751320	At sea, Brazil, January 2011 till March 2012	United Offshore Support GmbH & Co. KG, -----, -----	Bunker Delivery Note and representative sample were not provided.

Notes of protest received from the Administration of Hong Kong, China

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
COSCO THAILAND 9448798	Singapore, 5.5.2012	Consort Bunkers Pte Ltd, 31 Hong Kong Street Singapore 059670, Tel: +65 6344 3008 Fax: +65 6344 5745	The sulphur content on BDN: 3.41% m/m, The sulphur content after supplied and tested: 3.68% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number, etc.	Non-compliance issues
MOL EMINENCE 9407146	Singapore, 15.5.2012	Gloval Energy Trading Pte Ltd, 438 Alexandra Road #18-01/04 Alexandra Point Singapore 119958, Tel: +65 6559 1626 Fax: +65 6377 2512 e-mail: sales@genergytrading.com	The sulphur content on BDN: 3.45% m/m, The sulphur content after supplied and tested: 3.69% m/m
CSAV LEBU 9443463	Antwerp, Belgium, 2.6.2012	O.W. Bunker, Tavernierkaai 2 2000 Antwerpen Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 e-mail: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.07% m/m
CSAV LINGUE 9443475	Antwerp, Belgium, 11.6.2012	O.W. Bunker, Tavernierkaai 2 2000 Antwerpen Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 e-mail: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.07% m/m
ALIANCA ITAPOA 9448815	Singapore, 12.6.2012	Shell Eastern Trading (Pte) Ltd, -----, -----	The sulphur content on BDN: 3.30% m/m, The sulphur content after supplied and tested: 3.52% m/m
COSCO PRIDE 9472153	Singapore, 25.6.2012	Consort Bunkers Pte Ltd, 31 Hong Kong Street Singapore 059670, Tel: +65 6344 3008 Fax: +65 6344 5745	The sulphur content on BDN: 3.48% m/m, The sulphur content after supplied and tested: 3.68% m/m
COSCO DEVELOPMENT 9472139	Antwerp, Belgium, 1.7.2012	Chemoil Belgium N.V., Lambrechtschoekenlaan 145 Bus 4 – 2170 Antwerpen, Belgium, Tel: +32 3 645 7236	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.02% m/m
CSAV LINGUE 9443475	Antwerp, Belgium, 23.7.2012	O.W. Bunker, Tavernierkaai 2 2000 Antwerpen Belgium, Tel: +32 3 288 3600 Fax: +32 3 234 1874 e-mail: owbunker@owbunker.be	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.08% m/m